


FIG. 1  
(PRIOR ART)



Clamp Case	Op1 >=	Op2 >=	Op1 leading zeros	Op2 leading zeros	Total leading zeros
1.	0.100000.0000	0.000010.0000	0	4	4
2.	0.010000.0000	0.000100.0000	1	3	4
3.	0.001000.0000	0.001000.0000	2	2	4
4.	0.000100.0000	0.010000.0000	3	1	4
5.	0.000010.0000	0.100000.0000	4	0	4

FIG. 3

# Clamp Curves




FIG. 4

